

MULTIMETERS

=30 KA

MULTIMETERS PROTECTION FUSE LINKS



MULTIMETERS PROTECTION FUSE LINKS

CYLmultimeters
fuse links

DMM fuse links are specially designed for the protection of multimeters. They have fast acting characteristics and are available in two rated currents: 0,44A (440 mA) and 11A. Intended to carry 100% of rated current continuously. Maximum working voltage is 1000V AC/DC.



10x35	
U	1000V AC/DC
BREAKING CAPACITY	30kA

In (A)	REFERENCE	PACKING Uni /BOX
0,44	416005	10






11 **416010** 10



t-I CHARACTERISTICS



Prospective current (r.m.s. A)







PROTECTING THE WORLD

















